Discussion Item

3165 Martha Custis Drive - Resident Seeking Assistance for Rusted Casing on Kitchen Window

PF2 PF2 FOR NEW WORKORDER

Work Order History - 02/13/2019

Detailed Report

Lot/U	nit#: 8	4805	Account #: 84805 3165 F	Martha Custis Drive	Colleen C. Woomer			
W/O #	27,863	Create Date 01/23/2015 Summary :	W/O Type ROF Roof Repair Replace flashing	Authorization LS Loretta Samuels	<u>Active</u> NO	Closing Date 05/11/2016		
		Phone (1) :						
	Special Ins	tructions:	Plaster damage on bathroom ceiling					
	Detailed De	escription:	per staff (Duane) replaced flashing at s	stack pipe and check over roof SEE MAP				
			completed by NVR					
W/O #	28,047	<u>Create Date</u> 01/30/2015	<u>W/O Type</u> PNT Painting	Authorization LS Loretta Samuels	<u>Active</u> NO	Closing Date 08/16/2015		
		Summary :	Plaster repairs	EG Eoletta Galliteis	NO	06/16/2015		
		Phone (1):	·					
	Special Ins	tructions:	call to SCH					
	Detailed De	scription:	roof work completed- start plaster reparted with the reparted with the room of	air on the bathroom ceiling				
			2/6/15 Left message 703-575-8182 LS 2/23/15 Emailed h/o LS sch for 3/11/15 @ 7:30-8am LS 3/11/15 Scraped, closed 2 holes- prime 8/13/15 Scraped, primed, appiled es To closed by Loretta	ed SJ				
//O #	28,578	Create Date	W/O Type	Authorization	<u>Active</u>	Closing Date		
		03/05/2015	EXT Exterior Window Pane	AA Alonzo Alexander	NO	08/14/2015		
		Summary : Phone (1) :	William Laile					
	Detailed De		Re-glaze casement windows. Unit own	er complains of cracks. Please check all window	s. AA			
			Called h/o left a message there will be no call back closed by Loretta	a fee NW				
//O#	28,579	Create Date	W/O Type	Authorization	Active	Closing Date		
		03/05/2015	PLU Plumbing	AA Alonzo Alexander	NO	08/21/2015		
		Summary :	Water Bugs					
	Phone (1) : Detailed Description:		Please seal all pipe chase in crawlspace. Unit owner complains of water bugs entering unit. Please chech kitchen and batl for entry points.					
			Closed by Audit					
W/O #	28,580	Create Date	W/O Type	Authorization	Active	Closing Date		
	•	03/05/2015	PST Pest Control	AA Alonzo Alexander	NO	04/29/2015		
		Summary : Phone (1) :	Water Bugs/Termite Inspection					
1.	Special Insti	ructions:	Please contact unit owner prior to entry	AA				
1	Detailed Des	scription:	Please treat for water bugs. Unit permitting)	owner also complains of possible termi	tes at building 848, Please	e schedule (weath		
			Closed by Belinda Jones					

PF2 PF2 FOR NEW WORKORDER

Work Order History - 02/13/2019

Detailed Report


Lot/Ur	nit #:	84805	Account #: 84805	3165 Martha Custis Drive	Colleen C. Woomer			
W/O #	28,65	03/11/2015	W/O Type EXT Exterior	<u>Authorization</u> LS Loretta Samuels	Active Closing Date NO 08/14/2015			
		Summary : Phone (1) :	Broken windows					
	Special I	nstructions:	Please let h/o know when o	oming				
	Detailed	Description:	per staff (Duane) replace a	l broken windows and wire brush all the rust away and o	plaze properly			
			per Norman this is complet closed by Loretta	ed				
W/O #	31,75	9 <u>Create Date</u> 08/07/2015	<u>W/O Type</u> PLU Plumbing	<u>Authorization</u> LS Loretta Samuels	Active Closing Date NO 08/17/2015			
		Summary : Phone (1) :	Outside spigot					
	Special Ir	structions:	SCH for Thursday 8/*13/15					
	Detailed i	Description:	per staff (Sarah) please ins	tall a new outside spigot to the right of back door				
			8/13/15 Installed new spigot when and as we discussed (Woomer and managment) we also did an emergency water shu off per Alonzo as the h/o contractor can put valve in the bathroom SM LE 8-1150am Follow up for painters closed by Loretta					
W/O #	31,976	08/18/2015	<u>W/O Type</u> PNT Painting	<u>Authorization</u> LS Loretta Samuels	Active Closing Date NO 03/04/2016			
		Summary : Phone (1) :	Repairs					
ı	Detailed [Description:	per staff Plumbers- please Ref w/o # 31759	epair the plaster around the hose bib				
			completed DK closed by Loretta					
W/O #	39,606	Create Date	W/O Type	<u>Authorization</u>	Active Closing Date			
		08/24/2016	FI Facilities In	spector BJ Belinda Jones	NO 09/08/2016			
		Summary :	water leak inside ba	throom				
	Special In	Phone (1) : structions:	please call to echodule 703	472 5572				
	•	escription:	please call to schedule 703-472–5572 water leak is occuring agina in the bathroom area (Same as last year)					
		, coon parom	accept this time the leak is showing up in the middle of the bathroom ceiling.					
			Last year a roof repair was made, BUT there is a bathroom above this unit.					
			8/25/16 Tried to Call twice and phone ring once and then was a busy signal LS					
			9/7/16 moisture damage done by E & G NW Followup for plaster repairs closed by Iroetta		Repaired by plumbers. Additional repairs will be			

PF2 PF2 FOR NEW WORKORDER

Work Order History - 02/13/2019

Detailed Report

Lot/Ur	nit #: 8	4805	Account #: 84805	3165 Martha Custis	Drive	Colleen C. Woomer	
W/O #	50,431	Create Date 04/19/2018 Summary: Phone (1):	W/O Type EXT Exterior Casement Window	A	uthorization A Alonzo Alexander	<u>Active</u> NO	Closing Date 04/25/2018
	Special Ins Detailed De	tructions:	Please inspect casemer owner, AA		****	g. If repairs are needed, please s O responsiable NW	chedule with uni
V/O #	50,432 Special Inst	Create Date 04/19/2018 Summary : Phone (1) :	W/O Type PLU Plumbing Kayak and trailer 703-472-5572 Please coordinate with un	A	uthorization A Alonzo Alexander	<u>Active</u> NO	Closing Date 04/26/2018
	Detailed De		Please have Loretta to			ler that's attached to the pole ligh	: Lets see if w
110#	50,479	Create Date 04/23/2018 Summary : Phone (1) :	W/O Type USP Unit Serv Front door 703-472-5572	Au ices Program LS	uthorization S Loretta Samuels	<u>Active</u> NO	Closing Date 04/24/2018
	Special Inst Detailed De		703-575-8182 per h/o - New mail slot, D h/o cxl LS closed by Loretta	oor new knocker and new	lock		
IIO #	50,512	Create Date 04/24/2018 Summary : Phone (1) :	W/O Type USP Unit Serv cut lock 703-472-5572	ices Program G/	uthorization A Guy Andrew	<u>Active</u> NO	<u>Closing Date</u> 05/01/2018
	Detailed De		13:23cut lock to trailer w 04/25/18cut lockAdam requested by Association	ı - closed by Guy	pole in maintenance yard		
	50,609 Special Instr Detailed Des		W/O Type PST Pest Contermites 703-472-5572 email H/O when scheduled inspect for termite damage	rol G <i>A</i>	ithorization A Guy Andrew	<u>Active</u> NO	Closing Date 06/28/2018
			6/28/2018 scheduled treatment for turn Belinda Jones	esday July 2nd.			



From:

Scott Buchanan < buchananward4@gmail.com>

Sent:

Monday, September 23, 2019 8:08 PM

To:

Mark Miller

Cc:

Alonzo Alexander

Subject:

Re: ARs regarding rusted window, "grey areas"

Adding in Mark. As I recall normal routine maintenance is an owner's responsibility even in the old casement windows. This looks like zero upkeep has been going on here and so isn't some issue for the Association. Or am I wrong?

SB

On Sep 23, 2019, at 6:09 PM, c woomer < cwoomer2000@yahoo.com> wrote:


Hello Alonzo and Scott (ward IV)

This is an inquiry seeking assistance for rusted casings on my kitchen window.

I made an inquiry about a *month* ago regarding deteriorating casings and the person inspecting the casings said it didn't quality. Fast forward to a recent reading of "the gray areas" portion of our ARs and what I read indicated the inspector may not have been properly informed.

Here are pictures of the left and right side of my kitchen window showing the deterioration of the casings. I apologize for the large photo size and hope there is no problem downloading. Thank you for looking. Please get back to me as soon as is possible, as it is time sensitive.

Sincerely,
Colleene Woomer
Ward IV resident
3165 Martha Custis Dr. Bldg. 848



The above photo shows powdered ant bait in the area where they are entering in addition to the rust. Spraying outside the window has since destroyed the colony.



Window left side when inside.

<image3.jpeg>
Casings on the right side of the window.

From:

Mark Miller

Sent:

Tuesday, September 24, 2019 8:57 AM

To:

buchananward4@gmail.com

Cc:

Alonzo Alexander

Subject:

RE: ARs regarding rusted window, "grey areas"

Gray areas: #2: a. The Unit Owner is responsible for regular care and maintenance of window casings inside the case windows. If the Unit Owner takes the preventative maintenance steps suggested by the Association, then the Association is responsible for replacing rusted out window casings.

Clearly from this photo she has not maintained the inside. Alonzo mentioned that she said she may be replacing them, so not sure what she is asking? The section puts the responsibility on the unit owner.

From: Mark Miller

Sent: Monday, September 23, 2019 8:11 PM

To: buchananward4@gmail.com

Cc: Alonzo Alexander <aalexander@parkfairfax.info> **Subject:** Re: ARs regarding rusted window, "grey areas"

We paint and caulk the outside of the casements during the cycle. The inside is owner responsibility. We will have to take a look at closer. She's ward 4 I think and that's not until 2021

Mark Miller CMCA AMS General Manager Parkfairfax UOA

From: Scott Buchanan < buchananward4@gmail.com>
Sent: Monday, September 23, 2019 8:07:33 PM

To: Mark Miller <mmiller@parkfairfax.info>

Cc: Alonzo Alexander < <u>aalexander@parkfairfax.info</u>>
Subject: Re: ARs regarding rusted window, "grey areas"

Adding in Mark. As I recall normal routine maintenance is an owner's responsibility even in the old casement windows. This looks like zero upkeep has been going on here and so isn't some issue for the Association. Or am I wrong?

SB

On Sep 23, 2019, at 6:09 PM, c woomer < cwoomer2000@yahoo.com> wrote:


Hello Alonzo and Scott (ward IV)

This is an inquiry seeking assistance for rusted casings on my kitchen window.

I made an inquiry about a *month* ago regarding deteriorating casings and the person inspecting the casings said it didn't quality. Fast forward to a recent reading of "the gray areas" portion of our ARs and what I read indicated the inspector may not have been properly informed.

Here are pictures of the left and right side of my kitchen window showing the deterioration of the casings. I apologize for the large photo size and hope there is no problem downloading. Thank you for looking. Please get back to me as soon as is possible, as it is time sensitive.

Sincerely, Colleene Woomer Ward IV resident 3165 Martha Custis Dr. Bldg. 848



The above photo shows powdered ant bait in the area where they are entering in addition to the rust. Spraying outside the window has since destroyed the colony.



Window left side when inside.

<image3.jpeg>
Casings on the right side of the window.

From:

Alonzo Alexander

Sent:

Tuesday, September 24, 2019 10:48 AM

To:

c woomer

Cc:

buchananward4@gmail.com; Mark Miller; Jennifer Jett-Bowling

Subject:

RE: ARs regarding rusted window, "grey areas"

Attachments:

Approved Interp. of gray area responsibilities.docx

Hello Colleene:

The metal window frame to the interior is a unit owner responsibility. Please see attached Gray Areas of Responsibility (Area #2). The unit owner is responsible for the care and maintenance of the window casings inside the case windows. Based on a Facilities Inspection, there hasn't been much preventive maintenance conducted (interior) in the past. The Associations responsibility is the glazing of the windows (exterior) and seal.

Thx

Alonzo Alexander

From: c woomer < cwoomer2000@yahoo.com> Sent: Monday, September 23, 2019 6:10 PM

To: Alonzo Alexander <aalexander@parkfairfax.info>

Cc: buchananward4@gmail.com

Subject: ARs regarding rusted window, "grey areas"


Hello Alonzo and Scott (ward IV)

This is an inquiry seeking assistance for rusted casings on my kitchen window.

I made an inquiry about a *month* ago regarding deteriorating casings and the person inspecting the casings said it didn't quality. Fast forward to a recent reading of "the gray areas" portion of our ARs and what I read indicated the inspector may not have been properly informed.

Here are pictures of the left and right side of my kitchen window showing the deterioration of the casings. I apologize for the large photo size and hope there is no problem downloading. Thank you for looking. Please get back to me as soon as is possible, as it is time sensitive.

Sincerely,
Colleene Woomer
Ward IV resident
3165 Martha Custis Dr. Bldg. 848



The above photo shows powdered ant bait in the area where they are entering in addition to the rust. Spraying outside the window has since destroyed the colony.



Window left side when inside.



Casings on the right side of the window.

From: Mark Miller

Sent: Wednesday, September 25, 2019 9:48 AM

To: c woomer; Alonzo Alexander; buchananward4@gmail.com

Subject: RE: Repeat of what is being discussed

"Approved interpretation" meaning the Association reviewed the maintenance chart of responsibilities and clarified several "grey areas". Thus per the circled sections, the Association for item d. would repair or replace rotted or swollen doors. For Area #2, a. all interior maintenance of the casement windows is unit owner responsibility and b. exterior maintenance is the Associations responsibility. We only handle the exterior of the casements during the painting cycle or when an issue arises.

I am not sure we understand what you are asking or referring too? Based on the photos submitted, the inside of your windows need to be scraped and painted and per the language this is unit owner responsibility. Alonzo will however check the exterior as well and we will remedy any issues that are the Associations responsibility. Also seeing you had circled item d, are there any issues with your doors?

From: c woomer < cwoomer 2000@yahoo.com > Sent: Wednesday, September 25, 2019 9:38 AM

To: Alonzo Alexander <aalexander@parkfairfax.info>; Mark Miller <mmiller@parkfairfax.info>;

buchananward4@gmail.com

Subject: Repeat of what is being discussed

Alonzo, I'm resending, so you'll see the Heading, stating it's the approved interpretation.

Approved Interpretation of Gray Areas of Responsibilities

Area #1

- a. The Association is responsible for the replacement or repair of door sills, if proper upkeep is followed by the Unit Owner. However, the Unit Owner is responsible for weather stripping and the threshold.
- b. The Unit Owner is responsible for painting, varnishing or staining the interior of the door sill to ensure proper upkeep. If painting, varnishing or staining in snot done, and the door sill must be replaced, Parkfairfax will replace the door sill at the Unit Owner's expense. The Unit Owner is responsible for reporting damages to the door sill (or doors) to the Association Office so that it may respond in a timely fashion
- c. The Unit Owner is responsible for screen doors and their maintenance and replacement, as these are defined as an upgrade which do not have to be added to the unit.
- d. The Association is responsible for the cost of replacement or repair of rotted or swollen doors due to exterior causes. The Association may use whatever doors that it considers acceptable.

Arca #2

- a. The Unit Owner is responsible for regular care and maintenance of window casings inside the case windows. If the Unit Owner takes the preventative maintenance steps suggested by the Association, then the Association is responsible for replacing rusted out window casings.
- b. The Association is responsible for maintenance and repair of the outside of the casement windows and for the repair and replacement of the hinges. The Unit Owner is responsible for replacement or repair of glass and handles unless the Association is the cause of the breakage.

Area #3

a. The Unit Owner is responsible for immediately reporting initial indications of plaster and floor damage. The Association is responsible for repairs of plaster and floor damage due to roof or gutter leaks.

From: c woomer <cwoomer2000@yahoo.com>
Sent: Wednesday, September 25, 2019 10:21 AM

To: Mark Miller

Cc: Alonzo Alexander; buchananward4@gmail.com

Subject: Re: Repeat of what is being discussed

Your citing stopped short of the last sentence where if the painting fails that the association will replace rusted out casings.

The casings are perforated (rusted through) and painting will not correct the problem.

On Sep 25, 2019, at 9:47 AM, Mark Miller < mmiller@parkfairfax.info > wrote:

"Approved interpretation" meaning the Association reviewed the maintenance chart of responsibilities and clarified several "grey areas". Thus per the circled sections, the Association for item d. would repair or replace rotted or swollen doors. For Area #2, a. all interior maintenance of the casement windows is unit owner responsibility and b. exterior maintenance is the Associations responsibility. We only handle the exterior of the casements during the painting cycle or when an issue arises.

I am not sure we understand what you are asking or referring too? Based on the photos submitted, the inside of your windows need to be scraped and painted and per the language this is unit owner responsibility. Alonzo will however check the exterior as well and we will remedy any issues that are the Associations responsibility. Also seeing you had circled item d, are there any issues with your doors?

From: c woomer < cwoomer2000@yahoo.com Sent: Wednesday, September 25, 2019 9:38 AM

To: Alonzo Alexander <a learning parkfairfax.info >; Mark Miller <a learning parkfairfax.info >;

buchananward4@gmail.com

Subject: Repeat of what is being discussed

Alonzo, I'm resending, so you'll see the Heading, stating it's the approved interpretation.

<image001.jpg>

From:

Mark Miller

Sent:

Wednesday, September 25, 2019 10:25 AM

To:

c woomer

Cc:

Alonzo Alexander; buchananward4@gmail.com

Subject:

RE: Repeat of what is being discussed

The interior casing if properly maintained by the unit owner as prescribed would prevent rusting. Clearly based on the photos this has not been done. In essence are you asking that the Association replace the window?

From: c woomer < cwoomer 2000@yahoo.com>
Sent: Wednesday, September 25, 2019 10:21 AM
To: Mark Miller < mmiller @parkfairfay info>

To: Mark Miller <mmiller@parkfairfax.info>

Cc: Alonzo Alexander <aalexander@parkfairfax.info>; buchananward4@gmail.com

Subject: Re: Repeat of what is being discussed

Your citing stopped short of the last sentence where if the painting fails that the association will replace rusted out casings.

The casings are perforated (rusted through) and painting will not correct the problem.

On Sep 25, 2019, at 9:47 AM, Mark Miller mmiller@parkfairfax.info wrote:

"Approved interpretation" meaning the Association reviewed the maintenance chart of responsibilities and clarified several "grey areas". Thus per the circled sections, the Association for item d. would repair or replace rotted or swollen doors. For Area #2, a. all interior maintenance of the casement windows is unit owner responsibility and b. exterior maintenance is the Associations responsibility. We only handle the exterior of the casements during the painting cycle or when an issue arises.

I am not sure we understand what you are asking or referring too? Based on the photos submitted, the inside of your windows need to be scraped and painted and per the language this is unit owner responsibility. Alonzo will however check the exterior as well and we will remedy any issues that are the Associations responsibility. Also seeing you had circled item d, are there any issues with your doors?

From: c woomer < cwoomer2000@yahoo.com>
Sent: Wednesday, September 25, 2019 9:38 AM

To: Alonzo Alexander <a alexander@parkfairfax.info>; Mark Miller <mmiller@parkfairfax.info>;

buchananward4@gmail.com

Subject: Repeat of what is being discussed

Alonzo, I'm resending, so you'll see the Heading, stating it's the approved interpretation.

<image001.jpg>

From:

c woomer <cwoomer2000@yahoo.com>

Sent:

Friday, October 4, 2019 4:51 PM

To:

buchananward4@gmail.com; Mark Miller; Alonzo Alexander

Subject:

So now that I've clarified the damage to the window. Bldg 848

I have not had a reply regarding my window damage was not preventable by the owner.

I understand that the common answer would be to avoid any and all responsibility. This was not a common occurrence. Window well did fill up with water coming into the house and did cause the casings to rust through.

I am asking for your help in this matter. As you know it is also written that all windows on a side must be changed. So the expense is doubled! The clarified grey areas in regards to casings say that you can help. I very much need, and would appreciate help in this matter.

Colleene Woomer 3165 martha Custis drive. 848

From:

Scott Buchanan < buchananward4@gmail.com>

Sent:

Friday, October 4, 2019 5:06 PM

To:

c woomer

Cc:

Mark Miller; Alonzo Alexander

Subject:

Re: So now that I've clarified the damage to the window. Bldg 848

I think Management has provided their view here that this is out of scope of Association responsibility based upon past practice and interpretation, but the Board could take a different view. I'm happy to take the request to the Board and see if they are willing to consider the request. I can put it on next months agenda. If so, please send Dana any statements or information you'd like considered. We will by default include this email and what you've already sent in, but a summary and perhaps any other pictures current and past that show the nature of the damage would be useful. We just would need any additional information 5 business days ahead of the Board Meeting. You can certainly come and speak to the Board at the meeting offering more perspective during the residents forum at the beginning of the meeting, since we don't necessarily hear from owners during the consideration of the request and rely upon documentation. I think this is next step if you'd like to proceed.

SB

Scott Buchanan
President and Ward 4 Representative
Parkfairfax Board of Directors

- > On Oct 4, 2019, at 4:50 PM, c woomer <cwoomer2000@yahoo.com> wrote:
- > I have not had a reply regarding my window damage was not preventable by the owner.
- > I understand that the common answer would be to avoid any and all responsibility. This was not a common occurrence. Window well did fill up with water coming into the house and did cause the casings to rust through.
- > I am asking for your help in this matter. As you know it is also written that all windows on a side must be changed. So the expense is doubled! The clarified grey areas in regards to casings say that you can help. I very much need, and would appreciate help in this matter.
- > Colleene Woomer
- > 3165 martha Custis drive. 848

From:	Alonzo Alexander
Sent:	Wednesday, October 9, 2019 9:35 AM
То:	c woomer
Cc:	Jennifer Jett-Bowling; Mark Miller
Subject:	RE: new plantings (thanks!) they should have slurried the holes when they planted. called "watering in" daily watering in Fall is too much
	f can enter to inspect interior window frame. We could scrape, prime, and paint with a ld you like to proceed. Please Advise.
Thx	
Alonzo Alexander	
From: Alonzo Alexander	0 2010 0:25 ANA
Sent: Wednesday, October To: c woomer < cwoomer 20	
	(thanks!) they should have slurried the holes when they planted. called "watering in" daily
Didn't meant to say daily w	ratering, especially this time of the year. ©
From: c woomer < cwoome	r2000@yahoo.com>
Sent: Wednesday, October	·
To: Alonzo Alexander <aale< td=""><td></td></aale<>	
watering in Fall is too much	(thanks!) they should have slurried the holes when they planted. called "watering in" daily
but bless you!	
	o much. Get them a water tester. It's easy to overwater. That's why the e need to put peat moss in.
On Wednesday, October 9,	2019, 08:53:47 AM EDT, Alonzo Alexander aalexander@parkfairfax.info wrote:
Hello Colleen:	
Thanks for the reminder Wi	Il have staff put this area on their list for daily watering

Alonzo Alexander

From: c woomer < cwoomer2000@yahoo.com>
Sent: Wednesday, October 9, 2019 8:17 AM

To: Alonzo Alexander aalexander@parkfairfax.info

Subject: new plantings (thanks!) and remembering the planting steps. Will your crew water new plantings or do you need

owners to do it?

Good Morning Alonzo,

The electrical box near the Ravensworth playground was planted yesterday. They were chugging along pretty good with loosening the soil with the back hoe before planting. That should help with the moisture situation in the future as would adding peat moss for the newly developing roots as well as slurrying the hole which draws the soil really close to the roots as the water recedes.

I checked to see if the plants were watered---they WEREN'T. Can you remind them to return to water?

I believe that a You Tube video assignment on planting shrubs would be helpful. Some folks become gardeners because they have certain learning disabilities (whether they realize it or not) and learn best by doing, but also watching a video to encourage focus.

Can you make sure the proper steps are followed to ensure successful plantings? Please don't rely on verbal reminders. I assure you, for certain folks, that is very low on the retention of information scale.

From: c woomer <cwoomer2000@yahoo.com>
Sent: Wednesday, October 9, 2019 12:55 PM

To: buchananward4@gmail.com; Alonzo Alexander; Mark Miller

Subject: unit 3165 martha custis bldg 848 kitchen window

Scott,

Alonzo is offering to plaster and paint the interior of the window. The water from the overflowing downspout caused the interior to rust right through. It's not a patch job anymore. no Millennial would accept that. In addition the bottom of the window has bowed and will not longer accept a storm window.

Colleene Woomer

From: Scott Buchanan <buchananward4@gmail.com>

Sent: Wednesday, October 9, 2019 12:58 PM

To: c woomer

Cc: Alonzo Alexander; Mark Miller

Subject: Re: unit 3165 martha custis bldg 848 kitchen window

I believe that is all management has determined is appropriate here. The next step is that you may make a request to the Board as I outlined before. Only the Board can authorize work beyond the scope that management feels aligns with the Association's responsibilities under the ByLaws.

SB

On Oct 9, 2019, at 12:55 PM, c woomer < cwoomer2000@yahoo.com> wrote:

Scott,

Alonzo is offering to plaster and paint the interior of the window. The water from the overflowing downspout caused the interior to rust right through. It's not a patch job anymore. no Millennial would accept that. In addition the bottom of the window has bowed and will not longer accept a storm window.

Colleene Woomer

From: c woomer < cwoomer2000@yahoo.com>
Sent: Tuesday, September 24, 2019 6:18 PM

To: Mark Miller; Alonzo Alexander Cc: buchananward4@gmail.com

Subject: Window casings.

Alonzo, Mark & Scott, This is the document I was asking about. Wish we used identifiers on our documents.

Approved Interpretation of Gray Areas of Responsibilities

Area #1

- a. The Association is responsible for the replacement or repair of door sills, i followed by the Unit Owner. However, the Unit Owner is responsible for and the threshold.
- b. The Unit Owner is responsible for painting, varnishing or staining the inte sill to ensure proper upkeep. If painting, varnishing or staining in snot don sill must be replaced, Parkfairfax will replace the door sill at the Unit Own Unit Owner is responsible for reporting damages to the door sill (or doors) Association Office so that it may respond in a timely fashion
- c. The Unit Owner is responsible for screen doors and their maintenance and these are defined as an upgrade which do not have to be added to the unit.
- d. The Association is responsible for the cost of replacement or repair of rottdoors due to exterior causes. The Association may use whatever doors that acceptable.

Arca #2

- a. The Unit Owner is responsible for regular care and maintenance of windor the case windows. If the Unit Owner takes the preventative maintenance s the Association, then the Association is responsible for replacing rusted or casings.
- b. The Association is responsible for maintenance and repair of the outside o windows and for the repair and replacement of the hinges. The Unit Owne for replacement or repair of glass and handles unless the Association is the breakage.

Area #3

	3

at

From: c woomer < cwoomer2000@yahoo.com>
Sent: Wednesday, September 25, 2019 12:04 PM

To: Mark Miller

Cc: Alonzo Alexander; buchananward4@gmail.com

Subject: Re: Repeat / cont'd of what is being discussed 3165 Martha Custis Dr.

The water damage caused rusting from within the steel casing. This was caused by the downspout/drain outside of the window repeatedly clogging and spewing water*. At one point I begged for the aluminum well which was filling with water to be removed. The casings gradually rusted through from their interior. Prior to the approved interpretation/grey areas, the earlier form was always cited and no clarity existed, so nothing was done with regards to

the casing. When looking from the outside "there are no casings", just window-glass



frame.

..*

Because you asked, some notes on the doors. Originally I marked the screen-shot for My reference, but it does help the focus.

The <u>rear</u> entry is having problems with the wood containing the bolts/closure-lock tongue?, not the door itself. In spite of a dehumidifier running 24/7 the door has problems locking when seasonal moisture is an issue, and even now requires an extra push to line up to enable locking. Again, safety/security is my concern. The base/threshold rotted out years ago and was replaced by concrete on the exterior.

The <u>front</u> door fell off its hinges many years ago and was repaired. My concern is the strength of its wood. It feels dried out and weak, not providing protection from intrusion. There was a problem with the mechanical operation in the winter. It's currently functioning.

*this is an area where Former managers/boards have written in their newsletter updates that downspouts were being cleaned, but in fact did not take place, unbeknownst to the unit owner. Unless each one was checked, it was presumed that the work was accomplished. In later years I learned that unless I called to have it cleaned out it wasn't done. I understand that this is being addressed aggressively by current management/board and am very glad indeed! I never understood why it was allowed to continue for so long. Thank you for your efforts and dedication. The window problems would not have happened had we had our current programs in place.

On Sep 25, 2019, at 10:25 AM, Mark Miller < mmiller@parkfairfax.info > wrote:

The interior casing if properly maintained by the unit owner as prescribed would prevent rusting. Clearly based on the photos this has not been done. In essence are you asking that the Association replace the window?

From: c woomer < cwoomer2000@yahoo.com Sent: Wednesday, September 25, 2019 10:21 AM To: Mark Miller cwoomer2000@yahoo.com Sent: Wednesday, September 25, 2019 10:21 AM

Cc: Alonzo Alexander <a alexander@parkfairfax.info>; buchananward4@gmail.com

Subject: Re: Repeat of what is being discussed

Your citing stopped short of the last sentence where if the painting fails that the association will replace rusted out casings.

The casings are perforated (rusted through) and painting will not correct the problem.

On Sep 25, 2019, at 9:47 AM, Mark Miller < mmiller@parkfairfax.info> wrote:

"Approved interpretation" meaning the Association reviewed the maintenance chart of responsibilities and clarified several "grey areas". Thus per the circled sections, the Association for item d. would repair or replace rotted or swollen doors. For Area #2, a. all interior maintenance of the casement windows is unit owner responsibility and b. exterior maintenance is the Associations responsibility. We only handle the exterior of the casements during the painting cycle or when an issue arises.

I am not sure we understand what you are asking or referring too? Based on the photos submitted, the inside of your windows need to be scraped and painted and per the language this is unit owner responsibility. Alonzo will however check the exterior as well and we will remedy any issues that are the Associations responsibility. Also seeing you had circled item d, are there any issues with your doors?

From: c woomer < cwoomer2000@yahoo.com>
Sent: Wednesday, September 25, 2019 9:38 AM

To: Alonzo Alexander aalexander@parkfairfax.info; Mark Miller

<mmiller@parkfairfax.info>; buchananward4@gmail.com

Subject: Repeat of what is being discussed

Alonzo, I'm resending, so you'll see the Heading, stating it's the approved interpretation.

<image001.jpg>