June 2025 Reserve Expenditures Resolution Worksheet

Date: August 20, 2025

Suggested Motion:

"I move to approve the June 2025 Reserve Expenditures in the amount of \$225,828.66 with funds to come from GL 9901.015, Reserve Expenditures."

 2^{nd} :

Summary: Attached are the June 2025 Reserve Expenditures.

Vote:

	In Favor	Opposed	Abstained	Absent
Scott Buchanan				
Dave Bush				
Caitlin Counihan				
Lucille Eddy				
Elaine Lawler				
Jeff Lisanick				
Scott Mulrooney				
Mike Rothenberg				
Jim Wicker				

Codes	Reserve Item Description	Amount	Invoice #	Vendor	Invoice Description
					Waterproofing: Units 1925-1927; Excavate and water seal exterior at front of building between stoops.
95-9990101	Special Project 1	\$8,395.00	10227-05891	E&G Services	Excavate 6' depth, 3' wide x 16'. All hand-dug.
					Waterproofing: Units 1929-1931; Excavate and water seal exterior at front of building between stoops.
		\$6,282.44	10227-31689	E&G Services	Excavate 6' depth, 3' wide x 12'. All hand-dug.
		\$7,605.0 <u>0</u>	10227-41730	E&G Services	Crawlspace Venting: Installed 35'x3' PVC in crawlspace. Core drilled 3" hole on N. side of building. Installed exhaust 300 CFM exhaust fan. Poured gravel in well.
					Waterproofing: Units 1927-1929; Excavate and water seal exterior at front of building between stoops.
		\$13,148.00	10227-19293	E&G Services	Excavate 6' depth, 3' wide x 25'. All hand-dug.
		\$35,430.44			
95-9900100	Building Exterior	<u>\$1,150.00</u>	2025-0166	Almo Construction, Inc.	3919 Gunston Road; Removed and replaced the stone windowsill.
		\$1,100.00	2025-0172	Almo Construction, Inc.	3719 Gunston Road; Removed and replaced the stone windowsill.
		\$990.00	2025-0182	Almo Construction, Inc.	3316 Martha Custis Drive; Removed and replaced the stone windowsill.
				,	Lights out in the main parking lot at 3612 Valley Drive. Repaired lights after discovering a baby squirrel in
		<u>\$2,640.00</u>	25-0174	Lighting Maintenance	the fixture.
		\$3,226.8 <u>8</u>	2505-413088	TW Perry	10 HTL 87x28x3.5 Custom Triangle Louvers.
				,	
		<u>\$12,886.52</u>	2505-448081	TW Perry	40 HTL 87x28x3.5 Custom Triangle Louvers.
		\$17,771.4 <u>6</u>	H4603-521979	Home Depot	50 TimberTech/Azek Exterior Moulding Crown AZM-49 4"x3-5/8"x16' PVC. 450 TimberTech/Azek Exterior Moulding Shingle Mould AZM-210 11/16"x1-5/8"x16'.
					Services from April 25 to May 29, 2025, included a site visit to observe existing conditions at building 712
		\$2,584.00	220017660002	Walker Consultants	and communications with owners and contractors regarding 2025 façade work.
		\$42,348.86			
		342,346.60			
					Bldg. 707 Storm Drain Installation: Installed 30' of 4" schedule 40 PVC at the corner downspout at 3511
95-9901202	Riser Replacement & Repair	\$4,699.00	10227-077420	E&G Services	Valley Drive.
		\$4,699.00			
95-9901203	HVAC	¢E E16 00	S035530096.002	J&H Aitcheson	14 AOS 100187866 Burner Assembly for Waterheaters
32-3301203	Invac	<u>\$5,516.99</u>	3035530096.002	J&H AILCHESON	14 AO3 10010/000 Duriler Assembly for Waterneaters
		\$5,057.45	S035915116.001	J&H Aitcheson	30 AOS 100113151 Flame Sensor Rod Kit. 10 AOS 100271888 Spark Ignitor. 10 AOS 100191120 Spark Ignitor. (Waterheater Parts)
		\$566.79	S035915116.002	J&H Aitcheson	4 AOS 100113151 Flame Sensor Rod Kit. 1 AOS 100271888 Spark Ignitor. (Waterheater Parts)
		\$3,706.97	S035598104.002	J&H Aitcheson	4 B&G 1BL013LF Series PL 30B Lead Free. (Waterheater Parts)
		<u>\$2,878.57</u>	S035033419.001	J&H Aitcheson	5 AOS 100111040 Combines Controller F/BTH 199 100. (Waterheater Parts)
				C.L. Hibbard Plumbing,	Replaced the circuit board in the water heater in the building and adjusted the gas pressure. Bldg. 803
		<u>\$1,063.00</u>	i25921	Heating & Plumbing	found ground washer missing from CCB Board and gas valve defective. Replaced washer and gas valve.
		¢10 700 77			
1		\$18,789.77		1	

95-9900200	Building Interior		902608	Home Depot	Rental Unit 3554 MC - Washer & Dryer Replacement
95-9900200	Building interior		902008	потпе рерог	Rental Offit 5554 Mic - Washer & Dryer Replacement
		\$0.00			
		\$0.00			
95-9990102	Special Project 2	<u>\$13,992.47</u>	534QOM	LUX Foundation Solutions	1668 Fitzgerald Lane foundation repairs.
					Building 738 - Units 3348-3350 Gunston Road: Waterproofing - Excavate and water seal exterior rear of
		<u>\$3,113.75</u>	10227-335026	E&G Services	building. Excavate 6' depth, 3' wide x 16'. All hand dig.
		4 4.			Building 828 Settlement Assessments. Services for the period of May 1, 2025 to May 29, 2025 included
		\$1,550.01	220017920001	Walker Consultants	site visit to perform interior portion of field work.
		\$18,656.23			
95-9900401	Swimming Pool	\$175.85	9171346	Home Depot	9 Ft. Aluminum Market Tilt Patio Umbrella
33 3300401	Switting (CC)	\$54.86	8750121	Home Depot	5.5 LBS. Fillable Heavy-Duty Round Patio Umbrella Base.
		954.00	0730121	Home Bepot	5.5 EBS. Thirdsic Fically Buty Round Fund Offishering Buse.
		£220.74			
		\$230.71			
					Tile Repairs: 3706 Holmes Lane; replaced 1 tile. 3321 Coryell Lane; replaced 7 tiles and ridge cap. 3205
					Guntson Road; 3" pipe vent needed. 1751 Preston Road; replaced 12 tiles. 1727 Preston Road; replaced 7
					tiles. 3107 Valley Drive; replaced 6 tiles. 3142 Martha Custis Drive; tool measurements for replacing
95-9901222	Roof Maintenance	<u>\$4,850.00</u>	17926	Ruff Roofing	metal.
					Tile Repairs: 6668 Fitzgerald; needs a 40' K gutter & accessories. 3217 Ravensworth Place; replaced 8 tiles
					& cleared debris. 3451 Martha Custis Drive; replaced 7 tiles & recaulked chimney. Installed new I&W
					sheild. 3205 Gunston Road; replaced pipe vent. 3573 Martha Custis Drive; gutter loose, replaced hangers & screws. 33142 Martha Custis Drive; performed inspection. 3111 Valley Drive; replaced vent & 12
		\$11,053.00	17941	Ruff Roofing	broken tiles.
				J	Tile Repairs: 3744 Gunston Road; replaced damaged wood & replaced 10 tiles. 3107 Valley Drive;
					replaced 6 tiles. 3706 Holmes Lane; replaced 14 broken tiles. 1727 Preston Road; replaced 7 broken tiles.
		<u>\$2,925.00</u>	18007	Ruff Roofing	1751 Preston Road; replaced 13 broken tiles.
					Tile Repairs: 1637 Preston Road; replaced 4 tiles. 3325 Martha Custis Drive; replaced 24 tiles. 3326
		\$5,205.00	18033	Ruff Roofing	Martha Custis Drive; replaced 4 tiles. 3324 Martha Custis Drive; replaced 2 tiles.
			-5101		
					Tile Repairs: 3730 Holmes Lane; replaced 2 tiles. 1122 Valley Drive; replaced 9 tiles & 3 ridge caps. 3421
		\$2,285.00	18034	Ruff Roofing	Martha Custis Drive; replaced 3 tiles. 3492 Martha Custis Drive; replaced 2 tiles.
					Tile Repairs: 1668 Fizgerald Lane; replaced 40 ft of downspout. 3703 Lyons Lane; replaced 5 tiles. 3666
		<u>\$2,868.50</u>	18051	Ruff Roofing	Gunston Road; replaced 3 tiles. 1431 Martha Custis Drive; replaced damaged wood & 3 tiles.
		62.222.00	10101	Duff Daafina	Tile Penniss, 1670 Eitzgereld Langurennissed gutter, 2226, 2229 Camiell Langurenland 44 Miles
		\$2,333.00	18101	Ruff Roofing	Tile Repairs: 1670 Fitzgerald Lane; repaired gutter. 3326-3328 Coryell Lane; replaced 11 tiles.
					Tiles Repairs: 3472 Gunston Road; replaced 4 tiles. 1617 Fitzgerald Lane; replaced 4 tiles. 3218 Martha
		<u>\$2,139.00</u>	18102	Ruff Roofing	Custis Drive; roof inspection, vent in need of replacement.
		\$1,450.00	18103	Ruff Roofing	Tile Repairs: 3248 Martha Custis Drive; Used TPO & PVC to temporarily patch areas of tree damage.
		<u> </u>	13103	Nooning	The second secon
					Tile Repairs: 3617 Gunston; Replaced 10 tiles. 1607 Mt. Eagle; Replaced 9 tiles. 3142 Martha; inspected
		<u>\$2,467.50</u>	25967	Ruff Roofing	metal flashing. Needs to be replaced.
		-\$960.00			Roof Maintenance

		\$36.616.00			
		, ,			
95-9900502	Electrical Switchgear	<u>\$390.08</u>	568067	Home Depot	4 Breaker BR 150 Amp 2-Pole 10k
		\$390.08			
95-9901213	Waterproofing	\$775.00	1031	Envirotex Environmental LLC	Mold Inspection - 3111 Valley Drive.
		•			Mold - 3111 Valley Drive; Mobilized and installed air scrubbers with HEPA filters. Created a low-pressure
					environment to prevent the spread of any spores. Installed plastic cover from entrance door to stairs,
		<u>\$14,195.20</u>	3360-25-5		attic, and bathroom area.
					Change Order - 3111 Valley Drive: New installation and attic floor treatment. Bathroom rebuild; additional mold treatments. Removed and replaced drywall in the bathroom. Provided POD for additional
		\$17,881.37	3360-25-6		storage.
		\$32,851.57			
95-9990103	Special Project 3	\$7,890.00	10270-132001		Crawlspace Gas Piping Replacement: Bldg 214 (4 units). Installed 110 feet of 1" black gas line - anti- corrosion, scheduled 40 pipe. Test the gas line with 100lb air pressure for a minimum of 12 hours before connecting back to the riser. Painted and labeled line. Installed two risers and two ball valves. Trenched in crawlspace for 10'-20' black steel gas line.
		\$13,963.00	10227-125049		Crawlspace Gas Piping Replacement: Bldg 215 (6 units). Installed 110 feet of 1" black gas line - anti- corrosion, scheduled 40 pipe. Test the gas line with 100lb air pressure for a minimum of 12 hours before connecting back to the riser. Painted and labeled line. Installed two risers and two ball valves. Trenched in crawlspace for 10'-20' black steel gas line.
		\$13,963.00	10227-16222		Crawlspace Gas Piping Replacement: Bldg 216 (6 units). Installed 110 feet of 1" black gas line - anti- corrosion, scheduled 40 pipe. Test the gas line with 100lb air pressure for a minimum of 12 hours before connecting back to the riser. Painted and labeled line. Installed two risers and two ball valves. Trenched in crawlspace for 10'-20' black steel gas line.
		\$35,816.00			
	Total reserve expenses	\$225,828.66			