March 2019 Reserve Expenditures Resolution Worksheet

Date: May 15, 2019

Suggested Motion:

"I move to approve March 2019 Reserve Expenditures in the amount of \$154,104 with funds to come from GL 3200, Reserve Expenditures."

 2^{nd} :

Summary: Attached are the March 2019 Reserve Expenditures.

Vote:

	In Favor	Opposed	Abstained	Absent
Scott Buchanan				
Susan Cox				=======================================
James Konkel				
Rich Moha				
Kathy Schramek				
Nicholas Soto				
Maria Wildes				
Robin Woods				

			\$9,890.00		
Building 706: Excavate and water seal front of building 705, between stoops at 3301 and 3303 Valley Drive. Excavate 5' depth, 3' wide x 12'. Hand Dig. Clean wall and inspect for major cracks and voids. Mechanically blow dry wall and apply waterproofing membrane.	E&G	866-1706	\$5,445.00		
Building 108: Excavate and water seal front and side corner of building between stoops at 3213 and 33215 Gunston Road. Excavate 5' depth, 3' wide x 8'. Hand dig. Backfill and regrade. Clean wall and insepct for major cracks and voids. Mechanically blow dry wall and apply waterproofing membrane.	E&G	866-1108	\$4,445.00	Waterproofing	1.009
					F
			\$3,093.97		
Building 112: foundation rehabilitation contract- services for period of 1/1/19-1/31/19 included prepartion of contract for building 112.	SRG	13221	\$829.75		
High Priority Façade Repairs: Services for the period 1/1/19-1/31/19: included two site visits on 1/4/19 and 1/8/19 to survey cracks with unit 3221, building 712 and unit 3716, building 537 as well as preparation of site observation report and coordinator of site visit to unit 3206, building 716.	SRG	13219	\$1,875.72		
Bldgs 527, 845 & 929: Services for the period of 1/1/19-1/31/19: included various communications with the owner and contractor regarding bldgs 845 and 929 pricing as well as a review of Avon's bid for 845 and 929.	SRG	13220	\$388.50	Settlement	1.006
			\$9,100.00		
3419-3421 Valley Drive: performed asbestos abatement located within the attics	Envirotex	19787	\$2,500.00		
Maintenance Yard- picked up and disposed of bags that contain asbestos pipe insulation.	Envirotex	19774	\$3,650.00		
1420 Martha Custis Drive-Performed asbestos abatement in the attic	Envirotex	19771	\$2,950.00	Asbestos	1.003
Invoice Description	<u>Vendor</u>	Invoice #	Amount	Reserve Item Description	Code

				1.024						1.021			1.012	
				Gutters						Fascia Repairs			Railings	
\$478.50	\$675.00	\$678.50	\$678.50	\$265.00	\$10,000.00	\$450.00	\$825.00	\$625.00	\$5,400.00	\$2,700.00	\$1,695.00	\$1,375.00	\$320.00	
1033	20615	1032	1031	20657		1030	1432	1428	1418	1413		15133	15132	
Dynasty	NVR	Dynasty	Dynasty	NVR		Dynasty	Dynasty	Dynasty	Dynasty	Dynasty		Ravensworth Railing	Ravensworth Railing	
Building 230: installed gutter guards	3236 Valley Drive: replaced 25ft of upper roof gutter	Building 228: Installed gutter guards, sealed hole.	Building 226: Installed gutter guards, sealed hole.	1413 Martha Custis Drive- Properly re-installed gutter guard, sealed gutter/fascia edge		Building 920: fascia repair	3558 Martha Custis Drive- Repaired damaged fascia in rear.	3702 Ravensworthe Place- replaced small section of fascia in rear.	Bldg 801: full gable and fascia replacement.	Building 917: full gable and fascia replacement. Final balance due now \$2,7000.		3325 Martha Custis Drive- Single top railing	1111 Beverly Drive- Rail post repair	


										1.033				1.03			
	ŝ									Roofing				Mold			
\$2,765.00	\$489.60	\$539.60	\$539.60	\$110.00	\$110.00	\$110.00	\$110.00	\$265.00	\$110.00	\$110.00	\$21,650.00	\$1,950.00	\$7,900.00	\$11,800.00		\$3,465.50	\$690.00
20615	20563	20559	20610	20861	20888	20843	20842	20844	20777	20782		19763	19760	19787	-		1028
NVR	NVR	NVR	NVR	NVR	NVR	NVR	NVR	NVR	NVR	NVR		Envirotex	Envirotex	Envirotex			Dynasty
3236 Valley Drive: removed existing flat roofing & edge metal to roof deck, replaced any damaged decking at an additional cost of \$8.00/LF, mechanically fastened 1/2 inch fiberboard insulation over wood deck, fully adheared .060 EPDM membrane over fiber board, accomplished all seams, flashings & terminations in accordance with manufactures guide lines, installed all new edge metal, shop fabricated & installed coper edge & counter metal, cleaned up & hauled away all job related materials.	with new. Replaced tiles that were removed and sealed as needed. 3111 Ravensworth Place: removed existing pipe collar and replaced with new, replaced tiles that were removed and sealed as needed.	replaced tiles that were removed and sealed as needed. 3428 Martha Custis Drive: Removed existing pipe collar and replaced	3530 Valley Drive: removed existing pipe collar and replaced with new,	1024 Valley Drive: Re-secured 2 tile.	3451 Martha Custis Drive: Replaced 1 tile.	1712 Preston Road: Re-secured 2 tiles.	3466 Gunston Road: Replaced 1 tile.	1628 Mount Eagle Place: Replaced 3 tiles.	3317 Valley Drive: Replaced 2 broken tiles.	3207 Ravensworth Place: Replaced 2 broken tiles.		1673 Preston Road: performed mold encapsulation	3239 Ravensworth Place: performed mold remediation	3419-3421 Valley Drive: performed mold remediation located within the attics			Building 834: installed gutter guards

20730 20908 20908 20883 20783 19083 0 20614	\$2,885.00 20817 NVR 1715 Preston: removed approximately 350 tiles from rear and set aside for reinstallation, removed old wall flashing, shop fabricated new copper flashing to replace existing that was removed, installed new ice and water shield where old tiles were removed,
20730 NVR 20908 NVR 20908 NVR 20883 NVR 20783 NVR	NVR
20730 NVR 20908 NVR 20908 NVR 20883 NVR 20783 NVR	
20730 NVR 20908 NVR 20908 NVR 20883 NVR	\$6,668.80
20730 NVR 20908 NVR 20908 NVR 20883 NVR	NVR
20730 NVR 3303 Coryell La 20908 NVR 1605 Mount Ea 20883 NVR 3706 Gunston-	NVR
20730 NVR 20908 NVR	NVR
20730 NVR	NVR
20730 NVR	
COSIC NAL	NVR
20017 NIVE	\$110.00 20912 NVR 31
\$110.00 20919 NVR 3744 Holmes: Replaced 3 tiles.	NVR
\$110.00 20918 NVR 3245 Gunston: Replaced 2 tiles.	NVR
\$110.00 20914 NVR 3412 Gunston: Replaced 5 tiles.	NVR

Building 835: crawlspace pex piping	E&G	866-2835	\$10,185.00	Pex Piping	1.06
Building 801- full fascia replacement. <i>Reclassification from GL1.55 to</i> 1.021 fascia repair.	Dynasty	1418	-\$5,400.00	Louver/Vent Gable	1.55
			4.00		
(30) Wolf 1x12x18 trim board smooth, (40) Wolf 2-3/4 crown, (40) Wolf shingle moulding	Lansing	6770983	\$3,286.91		
(20) Wolf 1x6x18 trim board smooth	Lansing	6771372	\$647.46	Wood Trim	1.54
1502 Mount Eagle: tuck point wall and remove and replace broken bricks. 1534 & 1536 Mount Eagle: remove mortar joints from wall by the steps and remove broken bricks. Remove and replace brick at building wall along the steps. 1506 Mount Eagle: remove and replace 8lf of roll lack. remove all mortar joints along the steps.	Almo	2019-056	\$4,720.00	Tuckpointing	1.048
1715 Preston: Roof Inspection found damaged wall flashing	NVR		\$110.00 \$15,360.00		
1447 Martha- removed 175 tiles, checked for rotted wood, removed damaged wall flashing, installed ice and water shield, installed new copper flashing, sealed copper flashing, installed new tiles.	NVR	20633	\$3,267.00		
3326 Gunston- remoeved approximately 500 tiles from the front and rear of the bldg. removed old flashing, shop fabricated new flashing to replace existing, installed new flashing, reinstalled tiles, installed new ice and water shield where old tiles were removed, sealed as needed.	NVR	20616	\$5,961.00		

Sewer Line Repairs \$7,445.00 866-8831 E&G \$12,890.00 \$66-8831 E&G \$12,890.00 \$66-8529 E&G \$29,780.00 \$66-8533 E&G \$29,780.00 \$66-8535 E&G \$29,780.00 \$66-3954 E&G	Almo Construction 3314-3316- 3318 Ravensworth: Removed and replaced 53'x5' sidewalk, removed and replaced 33LF of header curb, removed and replaced 14.5LF of header curb	Almo Const	2019-058	\$5,904.90		
\$12,890.00 \$12,890.00 \$12,890.00 \$25,445.00 \$866-8831 E&G \$12,890.00 \$8,445.00 \$866-8529 E&G \$7,445.00 \$866-8533 E&G \$7,445.00 \$66-8535 E&G \$25,445.00 \$25,445.00 \$66-8535 E&G \$29,780.00	truction 3225 Gunston Road: replaced slab at rear door.	Almo Const	2018-604	\$1,100.00		
\$12,890.00 \$52,445.00 \$66-8831 E&G \$12,890.00 \$12,890.00 \$52,445.00 \$66-8529 E&G \$7,445.00 \$66-8533 E&G \$7,445.00 \$66-8535 E&G \$52,745.00 \$66-8535 E&G \$52,780.00					Concrete Sidewalks	6.021
\$12,890.00 \$12,89						
Storm Drain \$5,445.00 866-8831 E&G				\$29,780.00		
\$12,890.00 \$5,445.00 \$12,890.00 \$12,890.00 \$5,445.00 \$866-8529 \$8,445.00 \$8,445.00 \$866-8533 \$8,445.00 \$7,445.00 \$866-8535 \$866	Building 954: Install 86' of 4" schedule 40 pvc from downspouts, installed 12"x12" drain, hand dig, install (5) cleanouts, backfill and re-grade.	E&G	866-3954	<u>\$5,445.00</u>		
\$12,890.00 866-8831 E&G \$12,890.00 866-8831 E&G \$12,890.00 866-8529 E&G \$8,445.00 866-8533 E&G	Building 535: Install 120' of 4: schedule 40 pvc 3-5' depth into main storm drain at top of rear courtyard. 6" core drill into main storm drain. Hand dig. Install (2) cleanouts. Backfill and re-grade.	E&G	866-8535	\$7,445.00		
\$12,890.00 866-8831 E&G \$12,890.00 \$12,890.00 \$66-8831 E&G \$12,890.00 \$866-8529 E&G	Building 533: Install 150' of 4" schedule 40 pvc 3-5' depth into main storm drain at top of rear courtyard. 6" core drill into main storm drain. Hand dig. Installed (4) cleanouts. Backfill and re-grade.	E&G	866-8533	\$8,445.00		
Sewer Line Repairs \$7,445.00 866-8505 E&G \$5,445.00 866-8831 E&G \$12,890.00	Building 529: Install 40' of 4: schedule 40 pvc 3-5' depth into main storm drain at bottom of rear courtyard. Installed 100' of 6" schedule 40 pvc 3-5" depth to tie in buildings 533 and 535. 6" core drill into main storm drain. Installed (2) 18x18 storm drains. Hand dig. Installed (1) cleanout. Backfill and re-grade.	E&G	866-8529	\$8,445.00	Storm Drain	6.015
\$12,890.00 866-8505 E&G \$5,445.00 866-8831 E&G \$12,890.00						
Sewer Line Repairs \$7,445.00 866-8505 E&G \$5,445.00 866-8831 E&G				\$12,890.00		
Sewer Line Repairs \$7,445.00 866-8505 E&G	Building 831: Removed and installed 85' of 4" schedule 40 pvc in crawlspace. Hand dig. Backfill and re-grade.	E&G	866-8831	\$5,445.00		
	Building 508: Removed and installed 135' of 4" schedule 40 pvc in crawlspace. Hand dig. Backfill and re-grade.	E&G	866-8505	\$7,445.00	Sewer Line Repairs	1.069

Ī			6.033				
			Landscape Upgrades				
\$154,104.06	\$4,451.52	\$1,091.52	\$3,360.00	\$12,619.90	<u>\$4,580.00</u>	\$495.00	\$540.00
		929861	1002842		2019-052	2019-047	2019-055
		Neff Brothers Stone	G		Almo Construction	Almo Construction	Almo Construction
		Turfstone (279) 3 pallets	Woodlands: Natural area trash cleanup: removing trash, bottles, and plastic containers along the edge of the natural areas to a depth of 20' into the natural area in sections 2, 7, 8 & 9. Policing the entire natural area in section 5 for debris. All debris resulting from the job will be removed from the premises.		Almo Construction 3262-3260: repaired joints at flagstone walk, 3270-3284: repair joints at flagstone walk.	Almo Construction 3439 Martha- repaired corner of steps with Sika 122	Almo Construction 3301 Valley Drive: repair one step with sika 122



April 2019 Reserve Expenditures Resolution Worksheet

Date: May 15, 2019

Suggested Motion:

"I move to approve April 2019 Reserve Expenditures in the amount of \$218,082 with funds to come from GL 3200, Reserve Expenditures."

 2^{nd} :

Summary: Attached are the April 2019 Reserve Expenditures.

Vote:

	In Favor	Opposed	Abstained	Absent
Scott Buchanan				
Dan Courtney				
Susan Cox				
James Konkel				
Rich Moha				
Kathy Schramek				
Nicholas Soto				
Maria Wildes				
Robin Woods				

Code	Reserve Item Description	Amount	Invoice #	Vendor	Invoice Description
1.003	Asbestos	\$3,321.89	19791	Envirotex	Crawlspace Abatement building 835
		\$3,321.89	19730	Envirotex	Crawlspace Abatement building 309
		\$3,321.89	19791	Envirotex	Crawlspace Abatement building 835
		\$9,965.67			
1.006	Settlement	\$69,718.20	12146	AVON	Pay application # 1 for settlement work at building 112
		\$248.00	13364	SRG	Pre-bid summary letter building 112 period 2/1/19 to 2/28/19
		\$1,375.49	13367	SRG	Contract preperation building 112 period 2/1/19 to 2/28/19
		\$542.50	13221	SRG	527, 845, 929 Foundation Repair additional design hourly service period 2/1/19 to 2/28/19
		\$128.50	13316	SRG	Crack guage monitoring building 822 period 2/1/19 to 2/28/19
		\$861.00	13317	SRG	High priority Façade repairs crack gauge monitoring period 2/1/19 to 2/28/19 summary letter
		\$455.36	13365	SRG	High priority Façade repairs crack gauge monitoring period 2/1/19 to 2/28/19 site inspectrions buildings 111. 209, 537, 720, 830, 838, 845, 929 and pool A
		\$148.50	13361	SRG	Crack guage monitoring building 112 period 2/1/19 to 2/28/19
		\$1,558.50	13363	SRG	Services for period 12/1/18 to 2/28/19 crack monitoring and summary letter from site visit building 716
		\$914.86	13335	SRG	Additonal Services period 2/1/19 to 2/28/19 inspection of interior cracks at 718 units 3212 and 3214 Gunston Road
		\$140.00	13362	SRG	Crack guage monitoring building 206 period 2/1/19 to 2/28/19

		\$76,090.91			
1.009	Waterproofing	<u>\$6,445.00</u>	866-8310	E&G	Building 108: Excavate and water seal front and side corner of building between stoops at 3207 and 3209 Martha Custis Drive. Excavate 5' depth, 3' wide x 14'. Hand dig. Install (2) window wells. Backfill and regrade. Clean wall and insepct for major cracks and voids. Mechanically blow dry wall and apply waterproofing membrane.
		\$6,445.00			
1.021	Fascia Repairs	\$2,700.00	1093	Dynasty	Building 932: full gable and fascia replacement. Final balance due now \$2,7000.
		\$2,700.00			
1.024	Gutters	\$117.07	C-20915	NVR	3213 Gunston Road- Properly re-installed/realigned , sealed gutter/fascia edge, sealed mitre
		\$800.00	1082	Dynasty	Building 932: Installed gutter guards, sealed hole.
		<u>\$650.00</u>	1099	Dynasty	Building 912: Repaied downspout and crown molding.
		\$1,567.07			
1.033	Roofing	\$395.00	20558	NVR	3514 Gunston Road: Replaced 13 broken tiles.
	٥	\$489.60	20707	NVR	3416 Gunston Road: removed existing pipe collar and replaced with
		\$701.60	20725	NVR	3617 Gunston Road: Repair sheathing at eve and replace rotted 1x6 boards and 25 tiles
		\$1,212.07	20909	NVR	1016 Valley Drive: Removed 50 tiles, installed ice/and water shield and replaced and sealed tiles
		\$504.60	20882	NVR	3221 Gunston Road: removed existing pipe collar and replaced with new, replaced tiles that were removed and sealed as needed.
		\$395.00	20881	NVR	1102 Valley Drive: Re-placed 15 tiles.
		\$687.75	20610	NVR	3548 Marthas Custis Drive: Removed 22 tiles, installed ice/and water shield and replaced and sealed tiles

buidting 920 repair window flashing	DINASIT	1100	467.00	σ	
			6375 00	Poof Elashina	1003
				10.	
			\$7,554.42		
1631 Preston Road: replace 1 tile	NVR	20840	\$110.00		
3706 Gunston Road: repair plywood and hole at step down replace 4 tiles no rotted wood	NVR	20883	\$220.00		
3740 Gunston Road: Replace 5 tiles	NVR	20884	\$110.00		
1000 Valley Drive: Replaced 2 tiles	NVR	20885	\$110.00		
3757 Gunston Road: repair ridgecap and replace 4 tiles	NVR	20886	\$110.00		
1605 MT Eagle: replace 2 tiles	NVR	20908	\$110.00		
3102 Wellington: Removed existing pipe collar and replaced with new. Replaced tiles that were removed and sealed as needed.	NVR	20911	\$269.60	-	
3706 Gunston- Removed 4 tiles, found no rotted wood.	NVR	20883	\$220.00		
3103 Valley: replace 1 tile	NVR	20912	\$110.00		
3530 Valley Drive: Replaced 4 tiles.	NVR	20913	\$110.00		
3412 Gunston Road: Replaced 5 red tile.s	NVR	20914	\$110.00		
1511 MT Eagle repalce broken tiles, repair shifted tiles and seal mitre, clean gutter and seal wall falshing	NVR	20916	\$220.00		
3109 Valley Drive: Replaced 13 tiles.	NVR	20917	\$110.00		
3744 Holmes : Replaced 3 tiles.	NVR	20919	\$110.00		
3245 Gunston Road: replaced 2 tiles	NVR	20918	\$110.00		
3617 Gunston Road: Removed existing pipe collar and replaced with new. Replaced tiles that were removed and sealed as needed	NVR	20726	\$539.60		
1673 Preston Road: Removed existing pipe collar and replaced with new. Replaced tiles that were removed and sealed as needed.	NVR	20745	\$489.60		

1615-1636-1634 Fitzgerald: repair damaged brick and tuck point	ALMO	2019-067	\$2,875.00		
1659 Preston rear wall tuck point	ALMO	2019-061	\$3,150.00		
3300-3308 Gunston Tuck Point by downspouts	ALMO	2019-086	\$1,430.00	Building Masonry Tuckpointing	1.048
			\$23,940.00		
3734 Holmes- remoeved approximately 500 tiles from the front and rear of the bldg. removed old flashing, shop fabricated new flashing to replace existing, installed new flashing, reinstalled tiles, installed new ice and water shield where old tiles were removed, sealed as needed.	NVR	20623	\$5,961.00		
3630 Valley- remoeved approximately 365 tiles from the front and rear of the bldg. removed old flashing, shop fabricated new flashing to replace existing, installed new flashing, reinstalled tiles, installed new ice and water shield where old tiles were removed, sealed as needed.	NVR	20617	\$2,897.00		
3326 Gunston- remoeved approximately 350 tiles from the front and rear of the bldg. removed old flashing, shop fabricated new flashing to replace existing, installed new flashing, reinstalled tiles, installed new ice and water shield where old tiles were removed, sealed as needed.	NVR	20817	\$2,885.00		
3326 Gunston- remoeved approximately 500 tiles from the front and rear of the bldg. removed old flashing, shop fabricated new flashing to replace existing, installed new flashing, reinstalled tiles, installed new ice and water shield where old tiles were removed, sealed as needed.	NVR	20616	\$5,961.00		
FAR 20727 Remove 500 tiles, remove flashing, fabricate and install new copper flashing, install new ice and water shield, re-install tiles and seal flahing where needed.	NVR	20818	\$5,961.00		

					Concrete Sidewalks	6.021
\$1,190.00 2019-078 ALMO \$4,690.00 2019-064 ALMO \$13,335.00 2019-064 ALMO \$13,335.00 2019-064 ALMO \$13,335.00 2019-064 ALMO \$13,335.00 \$1903-159644 TW PERRY \$6,856.08 \$7,945.00 866-8954 E&G \$5,945.00 866-8914 E&G \$27,335.00 \$9,445.00 866-8914(a) E&G \$6,445.00 866-8912 E&G \$6,445.00 866-8912 E&G \$6,445.00 866-8912 E&G \$6,445.00 \$66-8912 E&G \$66-				\$15,890.00		
\$1,190.00 2019-078 ALMO \$4,690.00 2019-064 ALMO \$13,335.00 2019-064 ALMO \$13,335.00 1095 Dynasty \$1,456.08 1903-159644 TW PERRY \$6,856.08 \$27,945.00 866-8954 E&G \$27,335.00 \$27,335.00 866-8914 E&G \$27,335.00 \$9,445.00 866-8914 E&G	Building 912: Install 156' of 4" schedule 40 pvc 3-5' depth into main storm drain at top of rear courtyard. 6" core drill into main storm drain. Hand dig. Installed (3) 18" x 18"drain boxes. Backfill and re-grade.	E&G	866-8912	\$6,445.00		
\$1,190.00 2019-078 ALMO \$4,690.00 2019-064 ALMO \$13,335.00 2019-064 ALMO \$13,335.00 1095 Dynasty \$1,456.08 1903-159644 TW PERRY \$6,856.08 \$57,945.00 866-8954 E&G \$513,445.00 866-8914 E&G \$27,335.00 866-8914 E&G	Building 914: Rear of 1618 Fitzgerald. Install 240' feet of schedule 40 pvc 3-5' depth into main storm drain from hillside down to main storm drain.	E&G	866-8914(a)	\$9,445.00	Storm Drain	6.015
\$1,190.00 2019-078 ALMO \$4,690.00 2019-064 ALMO \$13,335.00 2019-064 ALMO \$13,335.00 1095 Dynasty \$1,456.08 1903-159644 TW PERRY \$6,856.08 Sewer Line Repairs \$7,945.00 866-8954 E&G \$533,445.00 866-8914 E&G \$27,335.00						
\$1,190.00 2019-078 ALMO \$4,690.00 2019-064 ALMO \$13,335.00 2019-064 ALMO \$13,335.00 1095 Dynasty \$1,456.08 1903-159644 TW PERRY \$6,856.08 Sewer Line Repairs \$7,945.00 866-8954 E&G \$5,945.00 866-8914 E&G				\$27,335.00		
\$1,190.00 2019-078 ALMO \$44,690.00 2019-064 ALMO \$13,335.00 2019-064 ALMO \$13,335.00 1095 Dynasty \$1,456.08 1903-159644 TW PERRY \$6,856.08 \$7,945.00 866-8954 E&G \$55,945.00 866-7835 E&G	Buildings 914-915 Fitzgerald: Replace damages terra coota sewer lines to and from sewer main clean out manhole. Snaked all line clear to street.	E&G	866-8914	\$13,445.00		
\$1,190.00 2019-078 ALMO \$4,690.00 2019-064 ALMO \$13,335.00 2019-064 ALMO Louver/Vent Gable \$5,400.00 1095 Dynasty \$1,456.08 1903-159644 TW PERRY \$6,856.08 Sewer Line Repairs \$7,945.00 866-8954 E&G	Building 835: Removed and installed 95' of 4" schedule 40 pvc in crawlspace. Hand dig. Backfill and re-grade.	E&G	866-7835	<u>\$5,945.00</u>		
\$1,190.00 2019-078 ALMO \$4,690.00 2019-064 ALMO \$13,335.00 1095 Dynasty \$1,456.08 1903-159644 TW PERRY \$6,856.08	Building 954: Removed and installed 135' of 4" schedule 40 pvc in crawlspace. Hand dig. Backfill and re-grade.	E&G	866-8954	\$7,945.00	Sewer Line Repairs	1.069
\$1,190.00 2019-078 ALMO \$4,690.00 2019-064 ALMO \$13,335.00 2019-064 Dynasty \$1,456.08 1903-159644 TW PERRY \$6,856.08						
\$1,190.00 2019-078 ALMO \$4,690.00 2019-064 ALMO \$13,335.00 2019-064 Dynasty Louver/Vent Gable \$5,400.00 1095 Dynasty \$1,456.08 1903-159644 TW PERRY				\$6,856.08		
\$1,190.00 2019-078 ALMO \$4,690.00 2019-064 ALMO \$13,335.00 Louver/Vent Gable \$5,400.00 1095 Dynasty			1903-159644	\$1,456.08		
2019-078 ALMO 2019-064 ALMO	Building 548- full fascia and gable replacement.	Dynasty	1095	\$5,400.00	Louver/Vent Gable	1.55
2019-078 ALMO 2019-064 ALMO						
2019-078 ALMO 2019-064 ALMO				\$13,335.00		
2019-078 ALMO	3210-3218 Valley rear: tuck poit form ground up to 3rd level	ALMO	2019-064	\$4,690.00		
	3748 Gunston Road: excavate 1.5' deep rear wall and tuck point in various locations	ALMO	2019-078	\$1,190.00		

e Upgrades \$10,085.00 1003109 CLS Turf restorations: 306, 312, 401, 514, 521, 804, 806, 810 and 822 \$950.00 1003145 CLS Remove shrubs in front of 112 for settlement work access \$11,035.00		
\$10,085.00 1003109 CLS \$950.00 1003145 CLS		
\$10,085.00 1003109 CLS		
	Landscape Upgrades	6.033
\$950.00 042319E ALASKA FENCE Repair fence Martha Custis (rear of 200'S)	Fences	6.024
		5110
\$14,418.00		
\$4,940.00 2019-047 Almo Construction 3102-3104-3108-3108 Valley Drive repairs flagstone walks, joints.		
\$4,052.00 2019-073 Almo Construction 3307 Valley Drive: remove and replace 4' x 4' sidewalk and 3531-3529 Martha Custis remove and repalce (2) 7' x 4' stoops, 45' x 4' of sidewlaks and 14' x 3.5' of walk with 2 steps		
\$1,519.00 2019-060 Almo Construction Spruce Island: Install (6) pads for new benches and building 316 remove and replace 3.5' x 3.5' of sidewalk		
\$3,907.00 2018-057 Almo Construction 3233-3231-3229 Ravensworth: Replace 6.5" x 5', 10' x 4' and 23' x 5' sidewalks; 3232 Ravensworth: Replace 9' x 5', 12' x 4' and 12LF header curb		