March 2024 Reserve Expenditures Resolution Worksheet

Date: May 15, 2024

Suggested Motion:

"I move to approve the March 2024 Reserve Expenditures in the amount of \$380,052.87 with funds to come from GL 9901.015, Reserve Expenditures."

2nd:

Summary: Attached are the March 2024 Reserve Expenditures.

Vote:

	In Favor	Opposed	Abstained	Absent
Scott Buchanan				
Dave Bush				
Matthew Larson				
Jeff Lisanick				
Amanda Mullan				
Scott Mulrooney				
Mike Rothenberg				
Jim Wicker				

Code	New codes	Reserve Item Description	Amount	Invoice #	Vendor	Invoice Description
1.054	9114.120	Building Wood Trim Replacement	<u>\$1,275.00</u>	2961	Dynasty	Cut 100 PVC plaques and dropped off to Ann McCord.
			\$1,275.00			
1.027	9901.010	Lighting Fixtures/Electrical	<u>\$100.00</u>	2404	Brian Mullins	Bldg 726. Remounted electric meter stack to wall.
			¢4,500,00	2400	Datas Mulling	Plds 707. Dealers dielectrical and die the least de annue and heiling and
			<u>\$4,500.00</u>	2408	Brian Mullins	Bldg 707. Replaced electrical panel in the laundry room and boiler room.
			<u>\$1,500.00</u>	2409	Brian Mullins	1401 Martha Custis Drive - Replaced electrical panel with new. Flipped panel to the living room.
			<u>\$1,500.00</u>	2410	Brian Mullins	1403 Martha Custis Drive - Replaced electrical panel with new. Flipped panel to the living room.
			\$7,600.00			
4.055			4500.00	22.12	. .	
1.055	9114.210	Bldg. Louver/Vent Gable Ends	<u>\$500.00</u>	2949	Dynasty	Bldg. 533 - Large Gable Fabrication
			<u>\$2,025.00</u>	2960	Dynasty	Bldg. 536- Large Gable Fabrication. Shingle repair at large gable.
			<u>\$3,450.34</u>	2402-J831TM	TW Perry	10 87x28x3.5 Custom Triangle Louver.
			\$5,975.34			
						3 Water Heater. AOSmith BTH-199 100234900 Cyclone 100 gal tall and 120 ft 11/4x60 L soft
1.075	9901.029	Water Heaters	<u>\$39,716.17</u>	S033052119.001	J&H Aitcheson	copper tube.
			\$39,716.17			
			\$39,710.17			
						Bldg. 109 and 111: Services for February 1, 2024, to February 29, 2024, included preparation of
1.006	9114.120	Building Settlement	<u>\$2,655.00</u>	220015700001	Walker Consultants	change order # 1 and kick-off meeting regarding foundation repairs.
						20 High Priority Bldgs. Services for January 1, 2024 to January 25, 2024. Site visits to bldgs. 109,
			<u>\$4,652.44</u>	220015300005	Walker Consultants	111, 822, 834, and 932 regarding settlement. Included communication with unit owners.
						Building 716. Services from January 26, 2024, to February 29, 2024. Observe the foundation and
			<u>\$9,352.78</u>	220014820012	Walker Consultants	façade repairs and prepare filed reports. Included communication with unit owners.
			<u>\$6,175.25</u>	12918	Avon Corporation	Building 732 - Structure Floor Rebuilding.
			\$110,042.30	12924	Avon Corporation	Foundation and façade repairs to building 716. 3202-3210 Gunston Road
			\$132,877.77			
1.021	9114.120	Fascia Repairs	<u>\$4,540.00</u>	2950	Dynasty	Bldg. 536 and 548 Fascia and Gable Replacement.
			<u>\$3,770.00</u>	2984	Dynasty	Bldg. 702 Fascia and Gable Replacement.

			\$3,770.00	2967	Dynasty	Bldg, 701 Fascia and Gable Replacement.
						60 AZEK Trim Boards 1x12x18. 60 AZEK Trim Boards 1x8x18. 60 AZEK Trim Boards 1x6x18. 80
			<u>\$15,936.59</u>	6734864-00	Lansing Building Products	AZEK Shingle Mould AZM210 11/16x2 5-8x16.
			\$28,016.59			
1.011	9901.011	Handrails	\$3,250.00	37051	Ravensworth Welding	1620 Ripon; Fabricated and installed exterior Iron Basic Vertical Picket Handrails (2)
			<u>\$3,250.00</u>	37052	Ravensworth Welding	3607 Gunston; Fabricated and installed exterior Iron Basic Vertical Picket Handrails (2)
			<u>\$3,250.00</u>	37053	Ravensworth Welding	3609 Gunston; Fabricated and installed exterior Iron Basic Vertical Picket Handrails (2)
			\$9,750.00			
1.033	9901.016	Roof Tiles	<u>\$1,777.50</u>	13656	Ruff Roofing	Tile Repairs: 3717 Gunston; reinstalled downspout. 3727 Holmes; replaced 2 broken tiles, 1340 Martha; replaced 2 broken tiles. 1238 Martha; replaced 1 tile.
			<u>\$938.00</u>	14005	Ruff Roofing	Tile Repairs: 3336 Gunston; replaced 23 roof tile.
			\$1,005.50	14014	Ruff Roofing	Tile Repairs: 3606 Greenway; replaced 1 tile. 1610 Ripon; repalced 3 tiles and asses copper to the bottom of the calley. Cleaned gutter.
						Tile Repairs: 3230 Wellington; Inspection - corner flashing and drip edge need to be repaired.
			<u>\$1,649.00</u>	14092	Ruff Roofing	3222 Ravesnworth; replaced 4 damaged tiles. 3716 Lyon; replaced 10 tiles. Tile Repairs. 1630 Mt. Eagle; replaced 24 tiles and 3 caps. 3142 Martha; Added 3' copper drip
			<u>\$1,804.50</u>	14093	Ruff Roofing	edge.
			<u>\$1,192.00</u>	14094	Ruff Roofing	Tile Repairs. 3336 Gunston; reinstalled 7 tiles. 3104 Martha; repaired 1 tile. 1610 Ripon; reinstalled 3 tiles.
			<u>\$645.00</u>	14095	Ruff Roofing	Tile Repairs. 3360 Gunston; replaced 3 tiles. 3520 Gunston; replaced 2 tiles and caulked gutters.
			<u>\$2,552.00</u>	14127	Ruff Roofing	Tile Repairs. 3230 Wellington; replaced rotten wood, copper corner flashing, drip edge and underlayment.
			<u>\$1,451.50</u>	14145	Ruff Roofing	Tile Repairs. Bldg. 504; replaced 23 tiles.
			<u>\$1,855.00</u>	14196	Ruff Roofing	Tile Repairs. 1734 Preston; performed inspection - Needs new roof on front porch. 1124 Valley; replaced 2 tiles. 3312 Coryell; replaced 4 tiles. 1620 Preston; replaced 1 tile. 1923 Quaker; replaced 1 tile.
			<u>\$1,050.00</u>	2927	Dynasty	Building 535 Shingle repair at middle rake board. Repaired high and low section. Installed felt paper.
			<u>\$1,110.00</u>	2928	Dynasty	Building 537 Shingle repair at middle rake board. Repaired high and low section. Installed felt paper.
			<u>\$975.00</u>	2929	Dynasty	Building 539 Shingle repair at middle rake board. Removed and re-installed shingles to correctly and securely installed new shingles.
			<u>\$1,550.00</u>	2985	Dynasty	Building 702 - Roof/shingle repairs at gabled ends.
			\$2,575.00	2951	Dynasty	Bldg. 533; minor shingle repairs at gable end. Bldg. 548; minor shingle repairs at gable end. Bldg. 204; Gable replacement due to squirrel.
			<u>\$1,850.00</u>	2966	Dynasty	Bldg. 701 - Roof shingle repairs at gable rake board end. Removed sections of damaged shingles and reset new shingles.
			\$23,980.00			
			+==,500100			

1.054	9114.210	Masonry Repairs	<u>\$16,500.00</u>	2024-0135	Almo Construction	Repaired wall in front of building 102. Repaired cracks on existing concrete wall with Sika Top 122. Ezcavated along wall and installed #5 rebar dowel with epoxy into the wall. Installed new footings, installed brick vaneer, formed and insalled new conctret cap.
			\$16,500.00			
	9141.100	Carpets & Flooring	<u>\$850.00</u>	3	Condezos Carpet Cleaners	3350 Gunston Road - Installed new padding in dining room. Carpet cleaning, disinfecting and deodorizing in the living room, dining room and the stairs.
			\$850.00			
6.021	9901.011	Concrete Sidewalk	<u>\$10,950.00</u>	2024-0148	Almo Construction	Bld. 814 replaced 51'x3.5 sidewalk and 4.5'x4 step. Bld. 810 replaced 20'x3.5 sidewalk. Between bldg. 810&814 parking lot; replaced 25'x4 sidewalk, 605x3.5 sidewalk and 25 LF of curb. Bld. 808; replaced 56'x4' sidewalk and replaced 28 LF of curb.
			\$10,950.00			
1.009	9114.210	Waterproofing	<u>\$5,445.00</u>	8669-34461	E&G Services	Bldg 925: Between stoops at 3459-3461 Martha Custis Drive. Excavate and water seal the building. Excavated 6' depth, 3' wide x 8'.
			<u>\$9,694.00</u>	8668-592057	E&G Services	Bldg 925: Between stoops at 3447-3449 Martha Custis Drive. Excavate and water seal the building. Excavated 6' depth, 3' wide x 8'. Bldg 925: Between stoops at 3449-3451 Martha Custis Drive. Excavate and water seal the
			<u>\$5,445.00</u>	8668-592059	E&G Services	building. Excavated 6' depth, 3' wide x 12'.
			<u>\$13,757.00</u>	8668-73946	E&G Services	Bldg 739: Between stoops at 3368 at left of building. Excavate and water seal the building. Excavated 5' depth, 3' wide x 34'.
			<u>\$10,101.00</u>	8668-35097	E&G Services	Bldg 707: Between stoops at 3507 and 3509 Valley Drive. Excavate and water seal the building. Excavated 5' depth, 3' wide x 25'.
			<u>\$6,445.00</u>	8668-35057	E&G Services	Bldg 707: Between stoops at 3505 and 3507 Valley Drive. Excavate and water seal the building. Excavated 6' depth, 3' wide x 12'. Bldg 519: Between stoops at 1256-1258 Martha Custis Drive. Excavate and water seal the
			<u>\$4,445.00</u>	8669-12569	E&G Services	Biog 519: Between stoops at 1256-1258 Martna Custis Drive. Excavate and water seal the building. Excavated 5' depth, 3' wide x 6'.
			\$55,332.00			
1.063	9901.008	Sewer Line Replacement	<u>\$47,230.00</u>	8669-814268	E&G Services	Bldg 810, 812 & 814. Water Main Replacement feeding 3 buildings.
			\$47,230.00			
		Total reserve expenses	\$380,052.87			